

SERVICE

TECHNICAL BULLETIN

New Special Tools –
Tail Lamp Adhesive Kit For XJ range

MODEL 2004 MY-ON
XJ range
VIN G00001-ON

Issue:

A new mandatory special service tool has been released, and will be distributed directly from the supplier. This mandatory tool is being issued free of charge.


Tool No.	Description
DS272990500 (Mandatory)	3M Applicator Gun and Plunger
DS272990484 (Optional)	3M Applicator Plunger

Tool DS272990500 will be required for repairing rear lamp assemblies on XJ vehicles. A procedure will be detailed in a Technical Bulletin.



NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

A new optional tool DS272990484 (spare plunger for DS272990500) has been set-up as a spare part via SPX for future requirements. This can be ordered as required directly from SPX using the contact details below.



Ensure that this service item has been supplied free of damage within your shipment. To report any damage or discrepancy pertaining to your shipment, please contact the SPX customer support line at 1-800-533-5338. Any claim against this shipment must be made within 30 days of receipt at your facility.