



XJ range

DATE 08/05

XJ206-03

SERVICE

TECHNICAL BULLETIN

Brake Caliper Flexible Hose – Washer Now Available Separately

MODEL 2004 MY-ON
XJ range
VIN G00001-ON

Issue:

The copper sealing washer for the brake caliper flexible hose is now available as a separate part. As a result, it is no longer necessary to replace the complete brake hose after disconnecting the hose from the brake caliper.

Action:

After disconnecting a brake hose from a caliper, replace only the washer. Do not replace an undamaged brake hose.

Global Technical Reference (GTR) Workshop Manual Information:

Dealer access: <https://hub.franchise.jaguar.com>

Internet access: <http://www.jaguartechno.com>

Parts Information:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Copper washer	C2C 31805	2 per caliper

Warranty Information:

Description	SRO	Time	Causal Part Number
N/A	-	-	-

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

