



XJ range

DATE 10/05

XJ501-20

SERVICE

TECHNICAL BULLETIN

Key Transmitters – Manual Programming – New Procedure

MODEL 2004 MY-ON
XJ range

VIN G00001-ON

Issue:

A new procedure has been developed to manually program the key transmitters for 2004 MY-ON XJ range vehicles.

Action:

To carry out the manual key transmitter learning procedure, follow the steps below.

Note: When carrying out steps 4 to 6, all current transmitters will be erased from memory. Ensure all transmitters to be programmed (up to 5) are available before proceeding.

Note: If at any stage two chirps are emitted, then an error has occurred, if this is the case, repeat the process from step 1. When carrying out steps 1 to 7, ensure no other transmitters are operated within range of the system.

1. Open driver door (door must be open throughout the programming process).
2. Pull turn signal stalk to the headlight flash position and hold.
3. Insert ignition key and turn to auxiliary position (position 1), then release the turn signal stalk.
4. Flash headlights five times (there will be an acknowledgment chirp from the sounder, and the PATS LED will flash once).

Note: Up to 5 transmitters can be programmed. Push the second transmitter button directly after programming the first, etc. Do not repeat the complete sequence as the first transmitter will be erased.

5. Push any transmitter button (there will be an acknowledgment chirp from the sounder, and the PATS LED will flash once).
6. Turn 'OFF' the ignition and remove the key, (there will be an acknowledgment chirp from the sounder, and the PATS LED will flash once).
7. Close driver door and check transmitter(s) functions.

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

Global Technical Reference (GTR) Workshop Manual Information:

Dealer access: <https://hub.franchise.jaguar.com>

Internet access: <http://www.jaguartechno.com>

Warranty Information:

Warranty claims should be submitted quoting the information found in the table below. This will result in payment of the stated time and, where applicable parts/miscellaneous expense codes as listed.

Description	SRO	Time	Causal Part Number
Manual key transmitter learning procedure	86.99.59	0.2 hrs.	C2C30685

Note: Repair procedures are under constant review, and therefore repair times are subject to change. The times quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.