

**S-TYPE**

DATE 04/00

S419-03

SERVICE**TECHNICAL BULLETIN****Aftermarket Rear Window Tint –
Interference With Reception of GPS Signal**MODEL 2000 MY-ON
S-TYPE

VIN L00001-ON

Issue:

Some 2000 MY-ON S-TYPE vehicles equipped with the Navigation System may experience improper operation if aftermarket window tinting has been applied to the rear window. Most window tints contain metal oxides which can disrupt the ability of the navigation antenna, which is located below the rear shelf, to receive the GPS signal.

Action:

Jaguar recommends that window tint should not be applied to the rear window and that the rear shelf be kept clear of metallic objects.

Contact the Jaguar Technical Hotline at 1-888-524-3577 if technical assistance is required.