



S-TYPE

DATE 05/01

S501-08

SERVICE

TECHNICAL BULLETIN

**Broken Fasteners –
Front Seat Squab Covers –
Replace Broken Fasteners**

MODEL 2000 MY-ON
S-TYPE
VIN L00001-ON

Issue:

This Technical Bulletin provides additional information about removing/installing the front seat back covers on S-TYPE vehicles.

In some cases when removing/installing the front seat back covers, the fixings are broken and are not always replaced.

Action:

When removing/installing the front seat back covers (refer to JTIS CD ROM, section 501-10, SRO 76.70.15), use great care not to break any of the mountings. To prevent the mountings being broken during the removal, carefully pry the fixings apart using a suitable flat blade trim tool, while fully supporting the weight of the seat back cover.

If any of the mountings are broken, replace them. If a mounting/retention point on the seat back cover is broken, replace the complete seat back cover.

Refer to JTIS CD ROM, section 501-10, SRO 76.70.15 for mounting/retention points.

Parts Information:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Fir tree fixing	XR8 23622	4
Seat back cover up to VIN L70000	XR8 11043 ***	1
Seat back cover from VIN L70000	XR8 21792 ***	1

*** add color suffix

Warranty Information:

This Technical Bulletin is for information only.

