



Sedan Range

DATE 6/95

15-14

**SERVICE**

# TECHNICAL BULLETIN

## Negative Battery Cable – Inadvertent Loosening

MODEL 1995 MY-ON  
Sedan Range

VIN  
720001-ON

**ISSUE:**

Disconnecting the battery negative cable from the battery and rotating it counterclockwise may cause the cable eyelet to loosen the nut at the body ground stud.

**ACTION:**

After reconnecting the battery negative cable, check the tightness of the nut on the cable ground stud.