



Sedan Range

DATE 2/95

15-26

**SERVICE**

**TECHNICAL BULLETIN**

In Car Entertainment – Radio Inoperative –  
Transit Protection

MODEL 1995 MY  
Sedan Range

VIN  
720001-ON

**ISSUE:**

The radio is inoperative on 1995 MY Sedan Range vehicles on delivery to dealers. The radio fuse is removed at the PDI center to protect the antenna during transit.

**ACTION:**

Install the radio fuse in all 1995 MY vehicles as part of dealer PDI.

1. Remove the 5 AMP (tan) fuse from the trunk spare fuse socket.
2. Install the 5 AMP (tan) fuse in position F10 of the fuse box (Illustration 1).




ILLUSTRATION 1