



Sedan Range

DATE **6/95**
Amended 3/97

18-07

SERVICE

TECHNICAL BULLETIN

Security System – Inclination and Intrusion Sensors Not Available

MODEL 1995-**97** MY
Sedan Range
VIN
720001-ON

Remove and destroy Bulletin 18-07, Date 6/95.
Replace with this Bulletin.
Revisions are marked with a bar and in **bold text**.

ISSUE:

Inclination and intrusion sensors cannot be added to 1995-**97** MY Sedan Range vehicles built to North American Specifications.

The parts microfiche includes part numbers for both sensors since it is a global document that serves all world markets.

North American Specification vehicles have a revised security and locking control module (SLCM) that does not support the addition of the inclination and/or intrusion sensors. In addition, the vehicle harness does not have connectors for these sensors.

For further information on Security System features, **refer to the appropriate model year Jaguar Product Guide issued to your sales department.**