

TECHNICAL BULLETIN



Throttle Deposits/Sticking Closed AJ16 Engines - Revised Idle Speed Adjustment Procedure

MODEL 1995-96 MY XJS (4.0L) Range DATE 6/97
VIN 194775-226645

19-40
Amended
2/99

Remove and destroy Bulletin 19-40, amended 8/97.
Replace with this Bulletin.
This bulletin is superseded by Bulletin 17-11, dated
12/98.

ISSUE:

This bulletin is superseded by Bulletin 17-11, dated 12/98.

ACTION:

Insert this sheet to maintain the continuity of the bulletin binder numbering system.